## **State of New Mexico** Energy, Minerals and Natural Resources Department Oil Conservation Division Hobbs District Office

HOBBS OCD

JUN 0 5 2013

BRAD	ENHE	AD T	FEST	REPO	ORT

BRADENHEAD TEST REPORT										
Operator Name PROVIDENCE ENERGY SERVICES, INC., dba Kelton Operating					30-025-32115		1			
Property Name SKELLY PENROSE B UNIT					W 74	ell No.	1			
7. Surface Location										
UL - Lot B	Section 8	Township 23S	Range 37E		Feet from 20	N/S Line NORTH	Feet From 2611	E/W Line EAST	County LEA	_
	Well Status									
Ta' D Well SHUT-IN NO NO			INJECTOR		PRODUCING Oil	0	DATE 5/31/2018	_		
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH										
OBSERVED DATA  If bradenhead flowed water, check all of the descriptions that apply:										

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csng	(E)Tubing
Pressure /	<u>0#</u>			45	45
Flow Characteristics					
Puff	N	Y / N	Y / N	Y / N	
Steady Flow	N	Y / N	Y / N	Y - N	
Surges	N	Y / N	Y / N	Y - N	
Down to nothing	N	Y / N	Y / N	Y / N	
Gas or Oil	N	Y/N	Y / N	Y / N	
Water	N	Y/N	Y/N	Y/N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
Remarks:				
Telliai ko.				
Cemented to Surface				

Signature:	Dun Kr	OIL CONSERVATION DIVISION	
Printed name: C. DALE KELTON		Entered into RBDMS	
Title: PRESIDENT		Re-test Q	
E-mail Address: providenceenergy@su	nddenlink.net		
Date: 06/04/2018	Phone: 432-661-1364		
	Witness:		