

HOBBS OCD

JUN 11 2018

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Chercon USA				API Number 30-025-25672				
Property Name Mexico L				Well No. #26				
1. Surface Location								
UL - Lot D	Section 5	Township 25S	Range 38E	Feet from 566	N/S Line N	Feet From 860	E/W Line W	County LEA

Well Status

TA'D WELL ☒ YES ☐ NO	SHUT-IN ☒ YES ☐ NO	INJECTOR ☐ INJ ☐ SWD	PRODUCER ☒ OIL ☐ GAS	DATE 5-17-18
--	--	---	--	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	N/A	N/A	N/A	60	NONE
Flow Characteristics					
Pull	Y / N	Y / N	Y / N	☒ Y ☐ N	CO2 ☐
Steady Flow	Y / N	Y / N	Y / N	☒ Y ☐ N	WTR ☐
Surges	Y / N	Y / N	Y / N	☒ Y ☐ N	GAS ☐
Down to nothing	Y / N	Y / N	Y / N	☒ Y ☐ N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	☒ Y ☐ N	Injected for
Water	Y / N	Y / N	Y / N	☒ Y ☐ N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

T/A Test

Signature:		OIL CONSERVATION DIVISION	
Printed name:		Entered into RBDMS	
Title:		Re-test	
E-mail Address:		X	
Date:	Phone:		
Witness: Gary Robinson			

INSTRUCTIONS ON BACK OF THIS FORM