

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

HOBBS OCD

JUN 11 2018

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Chevron USA		API Number 30-025-33413	
Property Name WDDU #		Well No. #156	

Surface Location

UL - Lot I	Section 32	Township 24S	Range 38E	Feet from 2000	N/S Line S	Feet From 1200	E/W Line E	County LEA
----------------------	----------------------	------------------------	---------------------	--------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

TA'D WELL ☒ YES ☐ NO	SHUT-IN ☒ YES ☐ NO	INJECTOR ☒ INJ ☐ SWD	PRODUCER ☐ OIL ☐ GAS	DATE 5-18-18
--	--	--	---	------------------------

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Csg	(E) Tubing
Pressure	0	N/A	N/A	0	NONE
Flow Characteristics					
Pull	Y / ☒ N	Y / N	Y / N	Y / ☒ N	CO2 ☐
Steady Flow	Y / ☒ N	Y / N	Y / N	Y / ☒ N	WTR ☐
Surges	Y / ☒ N	Y / N	Y / N	Y / ☒ N	GAS ☐
Down to nothing	☒ Y / N	Y / N	Y / N	☒ Y / N	Type of Fluid Injected for Waterflood if applies
Gas or Oil	Y / ☒ N	Y / N	Y / N	Y / ☒ N	
Water	Y / ☒ N	Y / N	Y / N	Y / ☒ N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

N/A

Signature:		OIL CONSERVATION DIVISION	
Printed name:		Entered into RBDMS	
Title:		Re-test	
E-mail Address:		X7	
Date:	Phone:		
Witness: Gary Robinson			

INSTRUCTIONS ON BACK OF THIS FORM