

HOBBS OCD

JUN 11 2018

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Chevron USA		API Number 30-025-33404	
Property Name W Dahrhede Drinkard		Well No. # 157	

Surface Location									
UL - Lot P	Section 31	Township 24s	Range 38E		Feet from 1275	N/S Line S	Feet From 400	E/W Line E	County LEA

Well Status									
TA'D WELL ☒ YES ☐ NO		SHUT-IN ☒ YES ☐ NO		INJECTOR INJ SWD		PRODUCER ☒ OIL ☐ GAS		DATE 5-17-18	

OBSERVED DATA

	(A) Surface	(B) Interim 1	(C) Interim 2	(D) Prod Casing	(E) Tubing
Pressure	0	N/A	N/A	0	None
Flow Characteristics					
Pull	Y/N	Y/N	Y/N	Y/N	CO2 ☐
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR ☐
Surges	Y/N	Y/N	Y/N	Y/N	GAS ☐
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid Injected for Waterflood if applies
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

T/A Test

Signature:		OIL CONSERVATION DIVISION	
Printed name:		Entered into RBDMS	
Title:		Re-test XZ	
E-mail Address:			
Date:	Phone:		
Witness: Gary Robinson			

INSTRUCTIONS ON BACK OF THIS FORM