

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

HOBBS OCD
JUN 22 2018

BRADENHEAD TEST REPORT

Operator Name Chevron U.S.A, INC	API Number 30025123280000
Property Name WEST DOLLARHIDE DRINKARD UNIT	Well No. 43

7. Surface Location

UL - Lot B	Section 32	Township 24	Range 33	Feet from 660	N/S Line N	Feet From 1980	E/W Line E	County LEA
----------------------	----------------------	-----------------------	--------------------	-------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

Well Status ACTIVE	SHUT-IN NO	PRODUCING INT	DATE 5-18-18
------------------------------	----------------------	-------------------------	------------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Intern	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csg	(E)Tubing
Pressure	0	0	NA	0	1450
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	
Steady Flow	Y/N	Y/N	Y/N	Y/N	
Surges	Y/N	Y/N	Y/N	Y/N	
Down to nothing	Y/N	Y/N	Y/N	Y/N	
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

INJECTING AT THIS TIME ___ WTR, ___ GAS, ___ CO2

MIT

Signature: [Signature]	OIL CONSERVATION DIVISION
Printed name: LaQuana Stigler	Entered into RBDMS
Title: ALCK	Re-test
E-mail Address: LaEQ@chevron.com	
Date: 5/18/18	
Phone:	
Witness: Gary Robinson	