

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

HOBBS OCD

JUN 22 2018

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Chevron U.S.A, INC	API Number 30025314880000
Property Name WEST DOLLARHIDE DRINKARD UNIT	Well No. 121

7. Surface Location

UL - Lot E	Section 32	Township 24	Range 38	Feet from 2176	N/S Line N	Feet From 656	E/W Line W	County LEA
----------------------	----------------------	-----------------------	--------------------	--------------------------	----------------------	-------------------------	----------------------	----------------------

Well Status

Well Status ACTIVE	SHUT-IN NO	PRODUCING INS	DATE 5-17-18
------------------------------	----------------------	-------------------------	------------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Casing	(E)Tubing
Pressure	0	N/A	N/A	0	1400
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	
Steady Flow	Y/N	Y/N	Y/N	Y/N	
Surges	Y/N	Y/N	Y/N	Y/N	
Down to nothing	Y/N	Y/N	Y/N	Y/N	
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks: INJECTING AT THIS TIME ___ WTR, ___ GAS, ___ CO2

Signature: L.M. W	OIL CONSERVATION DIVISION
Printed name: L.M. W	Entered into RBDMS
Title: PLCR	Re-test
E-mail Address: lw@chevron.com	
Date: 6/11/18	
Phone:	
Witness: Gary Rolenson	