Submit 1 Copy To Appropriate District Office	State of New Mexico Energy, Minerals and Natural Resources	Form C-103 Revised July 18, 2013
<u>District I</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240		WELL API NO.
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210 <u>District III</u> – (505) 334-6178	OIL CONSERVATION DIVISION	30-025-03518
District III – (505) 334-6178	1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd. A. 60 M 87410 District IV = (505) 47 460	Santa Fe, NM 87505	STATE S FEE 6. State Oil & Gas Lease No.
1000 Rio Brazos Rd. 476 340 87410 District IV – (505) 476 3460 1220 S. St. Francis Dr., Santa Faylor 87505	-10	E-1921
SUNDRY NOT	AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR CAPPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		7. Lease Name of Only Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		Yates "A"
1. Type of Well: Oil Well 🛛 Gas Well 🔲 Other		8. Well Number 2
2. Name of Operator Tandem Energy Corporation		9. OGRID Number 236183
3. Address of Operator		10. Pool name or Wildcat
5065 Westheimer Rd, Ste 920, Houston, TX 77056		North San Simon Yates
4. Well Location		Herait Gait Gillion Fales
Unit Letter K :	1981 feet from the South line and	1982 feet from the West line
Section 29	Township 21S Range 35E	NMPM County Lea
	11. Elevation (Show whether DR, RKB, RT, GR, etc.	
	3657 DF	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INT		SEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WOR	
TEMPORARILY ABANDON PULL OR ALTER CASING	CHANGE PLANS COMMENCE DR MULTIPLE COMPL CASING/CEMEN	
DOWNHOLE COMMINGLE	MOETH LE COMP E	1 308
CLOSED-LOOP SYSTEM		
OTHER:	☐ OTHER: Replace	e bad tubing to bring well back on 🔯
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of		
proposed completion or recompletion.		
5/21/2018 MIRLLINOR ROOM WIRODS & RUMB. SISDEN		
MIRU WOR POOH W/RODS & PUMP. SISDFN.		
5/22/2018		
POOH W/TBG LAY DOWN 5 BAD JTS RU TBG TESTERS TEST TBG TEST TBG GIH TO 5000PSI BLEW 1JT. SISDFN		
5/23/2018		
CREW LOADED TBG AT YARD HAULED TO THE YATES. RIH W/6JTS OF TBG CHANGE OVER TO RUN RODS. PU NEW		
PMP RIH W/PMP AND RODS. HWO NUKT TEST TBG TO 500PSI GOOD PA. RDMO		
Spud Date:	Rig Release Date:	
	5/23/2018	
		•
I hereby certify that the information ab	ove is true and complete to the best of my knowledg	e and belief.
SIGNATURE	TITLE IT Manager	DATE 6/15/2018
Type or print name Chris Sanders E-mail address: ChrisS@T5Energy.com PHONE: 713-987-7318		
1/- /- 10		
APPROVED BY: DATE 6/25/2018		
Conditions of Approval (if any):		
V		