

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Chevron U.S.A, INC	³ API Number 30025122790000
Property Name WEST DOLLARHIDE DRINKARD UNIT	Well No. 51

⁷ Surface Location

UL - Lot H	Section 31	Township 24	Range 38	Feet from 2310	N/S Line N	Feet From 330	E/W Line E	County LEA
----------------------	----------------------	-----------------------	--------------------	--------------------------	----------------------	-------------------------	----------------------	----------------------

Well Status

Well Status ACTIVE	SHUT-IN NO	PRODUCING INT	DATE 5-17-18
------------------------------	----------------------	-------------------------	------------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA



If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csgng	(E)Tubing
Pressure	0	0	N/A	0	1350
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	
Steady Flow	Y/N	Y/N	Y/N	Y/N	
Surges	Y/N	Y/N	Y/N	Y/N	
Down to nothing	Y/N	Y/N	Y/N	Y/N	
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:	INJECTING AT THIS TIME ___ WTR, ___ GAS, ___ CO2
----------	--

Signature: 	OIL CONSERVATION DIVISION
Printed name: L. N. Wright	Entered into RBDMS
Title: ALCN	Re-test 
E-mail Address: lwright@chevron.com	
Date: 6/11/18	
Phone: 432-270-8381	
Witness: Gary Robinson	