

HOBBS O&D
JUN 22 2018
RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Chevron U.S.A, INC	³ API Number 30025123470000
Property Name WEST DOLLARHIDE DRINKARD UNIT	Well No. 73

7. Surface Location

UL - Lot N	Section 33	Township 24	Range 38	Feet from 560	N/S Line S	Feet From 780	E/W Line E	County LEA
----------------------	----------------------	-----------------------	--------------------	-------------------------	----------------------	-------------------------	----------------------	----------------------

Well Status

Well Status Active	SHUT-IN No	PRODUCING INTJ	DATE 5-17-18
------------------------------	----------------------	--------------------------	------------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csgng	(E)Tubing
Pressure	0	N/A	N/A	0	1200
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	
Steady Flow	Y/N	Y/N	Y/N	Y/N	
Surges	Y/N	Y/N	Y/N	Y/N	
Down to nothing	Y/N	Y/N	Y/N	Y/N	
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks: INJECTING AT THIS TIME ___ WTR, ___ GAS, ___ CO2

Signature: [Signature]	OIL CONSERVATION DIVISION
Printed name: L. Q. [Signature]	Entered into RBDMS
Title: ALCR	Re-test [Signature]
E-mail Address: lucy@chevron.com	
Date: 6/11/18	
Phone: 432-270-0805	
Witness: [Signature]	