

State of New Mexico
Energy, Minerals and Natural Resources Department
HOBBS OCD Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

JUN 22 2018	Operator Name Chevron U.S.A, INC	³ API Number 30025123490000
RECEIVED	Property Name WEST DOLLARHIDE DRINKARD UNIT	Well No. 56

7. Surface Location									
UL - Lot	Section	Township	Range		Feet from	N/S Line	Feet From	E/W Line	County
E	33	24	38		2310	N	330	W	LEA

Well Status				
Well Status ACTIVE	SHUT-IN	PRODUCING INJ	DATE 6-5-18	

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csng	(E)Tubing
Pressure	0	N/A	N/A	0	0
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	
Steady Flow	Y/N	Y/N	Y/N	Y/N	
Surges	Y/N	Y/N	Y/N	Y/N	
Down to nothing	Y/N	Y/N	Y/N	Y/N	
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks: Well shut in for land remediation	INJECTING AT THIS TIME ___ WTR, ___ GAS, ___ CO2
--	--

Signature: [Signature]	OIL CONSERVATION DIVISION
Printed name: Loquayne Wright	Entered into RBDMS
Title: ALCK	Re-test
E-mail Address: LWEP@Chevron.com	
Date: 5/18/18	
Phone: 432-271-8389	
Witness: Dary Robinson	