

HOBBS OCD

State of New Mexico

Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED DENHEAD TEST REPORT

Operator Name Apache Corporation	API Number #30-025-42055
Property Name WARNst AM 2	Well No. 27


Surface Location									
UT. Loc 7C	Section 6	Township 18S	Range 35E	Feet from 330'	N/S Line FNL	Feet from 2310'	E/W Line FWL	County Lea	

Well Status									
TA'D WELL YES ☐ NO ☒	SHUT-IN YES ☐ NO ☒	INJ ☐	INJECTOR ☐	SWD ☐	OIL ☒	PRODUCER ☐	GAS ☐	DATE 6/29/18	

OBSERVED DATA

	(A) Surface	(B) Interim(1)	(C) Interim(2)	(D) Prod Casing	(E) Tubing
Pressure	0	0	—	20	20
Flow Characteristics					
Pull	Y/N	Y/N	Y/N	Y/N	CO2 ☐
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR ☐
Surges	Y/N	Y/N	Y/N	Y/N	GAS ☐
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Injected by
Water	Y/N	Y/N	Y/N	Y/N	Water level if
					applies

Remarks - Please state for each string (A, B, C, D, E) pertinent information regarding bleed down or continuous build up if applies.

Signature:		OIL CONSERVATION DIVISION	
Printed name: Albert DeLa Cruz		Entered into RBDMS	
Title: Pumper		Re-test	
E-mail Address: albert.delacruz@apachecorp.com			
Date:	Phone:		
	Witness: [Signature]		

INSTRUCTIONS ON BACK OF THIS FORM