

HOBBS OCD
JUL 30 2018
RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Apache Corp	API Number 30-225-55667
Property Name NMG SAN	Well No. 611

Surface Location

BL - Lot K	Section 25	Township 19S	Range 37E	Feet from 1000	N/S Line S	Feet From 1900	E/W Line W	County Lea
----------------------	----------------------	------------------------	---------------------	--------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status


TA'D WELL YES	SHUT-IN NO	INJECTOR NO	SWD NO	PRODUCER OIL	GAS NO	DATE 6-20-2018
-------------------------	----------------------	-----------------------	------------------	------------------------	------------------	--------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	0	N/A	0	600
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 —
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR —
Surges	Y/N	Y/N	Y/N	Y/N	GAS —
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid Injected for Waterflood if applies
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Prod. csg. had slight water

Signature: 	OIL CONSERVATION DIVISION
Printed name: Jim Ellison	Entered into RBDMS
Title: Tech	Re-test
E-mail Address:	
Date:	
Phone: 575-441-7734	
Witness: Doug Lorman	