

HOBBS OCD
JUL 30 2018
RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Apache Corp	API Number 30-025-05755
Property Name NMGSAU	Well No. 1015 (015)

1. Surface Location

UL - Lot 0	Section 30	Township 19S	Range 37E	Feet from 330	N/S Line S	Feet From 2310	E/W Line E	County Lea
----------------------	----------------------	------------------------	---------------------	-------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status


TA'D WELL YES ☐ NO ☒	SHUT-IN YES ☐ NO ☒	INJECTOR IN ☒ SWD ☐	OIL PRODUCER OIL ☐ GAS ☐	DATE 6-20-2018
--	--	---	---	--------------------------

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Csg	(E) Tubing
Pressure	0	0	0	0	640
Flow Characteristics					
Puff	Y/N ☒	Y/N ☒	Y/N ☒	Y/N ☒	CO2 ☐
Steady Flow	Y/N ☒	Y/N ☒	Y/N ☒	Y/N ☒	WTR ☒
Surges	Y/N ☒	Y/N ☒	Y/N ☒	Y/N ☒	GAS ☐
Down to nothing	Y/N ☒	Y/N ☒	Y/N ☒	Y/N ☒	Type of Fluid Injected for Waterflood if applies.
Gas or Oil	Y/N ☒	Y/N ☒	Y/N ☒	Y/N ☒	
Water	Y/N ☒	Y/N ☒	Y/N ☒	Y/N ☒	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Prod. csg. slight fluid

Signature: 	OIL CONSERVATION DIVISION
Printed name: Jim Ellison	Entered into RBDMS
Title: Tech	Re-test
E-mail Address:	
Date:	
Phone: 505-441-7734	
Witness: Darryl Johnson	