

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

HOBBS OCD
JUL 30 2018
RECEIVED

Operator Name Apache Corp	* API Number 30-025-05781
Property Name NMGSAU	Well No. 1606 (1606)

2. Surface Location

UL Lot F	Section 32	Township 19S	Range 77E	Feet from 1980	N/S Line N	Feet From 1980	E/W Line W	County Lea
--------------------	----------------------	------------------------	---------------------	--------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status



TA'D WELL YES ☒ NO ☐	SHUT-IN YES ☐ NO ☒	INJECTOR ☒	SWD	OIL PRODUCER	GAS	DATE 6-20-18
--	--	---	-----	--------------	-----	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	0	N/A	0	920
Flow Characteristics					
Puff	Y ☒ N ☐	Y ☒ N ☐	Y ☐ N ☒	Y ☒ N ☐	CO2 ☐
Steady Flow	Y ☒ N ☐	Y ☒ N ☐	Y ☐ N ☒	Y ☒ N ☐	WTR ☒
Surges	Y ☒ N ☐	Y ☒ N ☐	Y ☐ N ☒	Y ☒ N ☐	GAS ☐
Down to nothing	Y ☒ N ☐	Y ☒ N ☐	Y ☐ N ☒	Y ☒ N ☐	Type of Fluid Injected for Waterflood if applies.
Gas or Oil	Y ☒ N ☐	Y ☒ N ☐	Y ☐ N ☒	Y ☒ N ☐	
Water	Y ☒ N ☐	Y ☒ N ☐	Y ☐ N ☒	Y ☒ N ☐	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Prod. Csg. had slight fluid

Signature: 	OIL CONSERVATION DIVISION
Printed name: J. Ellison	Entered into RBDMS
Title: Tech	Re-test
E-mail Address:	
Date:	
Phone: 575-441-5751	
Witness: Dave Robinson	