

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Dwight A. Tipton					API Number 30-025-31000				
Property Name SUNRAY A 6822 LTD					Well No. #1				
Surface Location									
U/Lot 0	Section 36	Township 9S	Range 33E	Feet from 990	N/S Line 5	Feet From 1980	E/W Line 6	County LEA	

Well Status		DATE 7-16-18	
TA'D WELL YES	NO ☒ YES	SHUT-IN NO	INJ ☒ SWD
OIL		GAS	

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Csg	(E) Tubing
Pressure	0	N/A	N/A	0	0
Flow Characteristics					
Pull	Y/N	Y/N	Y/N	Y/N	CO2 ☐
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR ☒
Surges	Y/N	Y/N	Y/N	Y/N	GAS ☐
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood if applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Post Workover
Need C-103 sent to ocds office
Packer & setting + perfs.

Called Justin to send us C-103- 7/23/18 gmb

Signature:		OIL CONSERVATION DIVISION	
Printed name:		Entered into RBDMS	
Title:		Re-test	
E-mail Address:		JMB	
Date:	Phone:		
Witness: Gary Rolinson			

INSTRUCTIONS ON BACK OF THIS FORM

