

HOBBS

AUG 3 2018

RECEIVED

HOBBS OCD

AUG 3 2018

District I
1623 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-6720

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Lime Rock Resources II-A, L.P.		API Number 300252417600000
Property Name North Vacuum ABO North Unit 3-1		Well No. 001

Surface Location

UT - Lat J	Section 1	Township 17S	Range 34E	Feet from 1780	N/S Line S	Feet from 2000	E/W Line E	County Lea
---------------	--------------	-----------------	--------------	-------------------	---------------	-------------------	---------------	---------------

Well Status

TA'D WELL YES	SHUT-IN YES	INJECTOR NO	SWD OIL	PRODUCER GAS	DATE 8/3/18
------------------	----------------	----------------	------------	-----------------	----------------

OBSERVED DATA

	(A) Surface	(B) Internu(1)	(C) Internu(2)	(D) Prod Casing	(E) Tubing
Pressure	Ø	Ø		Ø	3800
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ✓
Surges	Y / N	Y / N	Y / N	Y / N	GAS
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of fluid injected for waterflood if applicable
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: <i>Eddie Elliott</i>		OIL CONSERVATION DIVISION
Printed name: Eddie Elliott		Entered into RBDMS
Title: Production Foreman		Re-test <i>jm</i>
E-mail Address: eelliott@limerockresources.com		
Date: 8/3/18	Phone: 432-413-0429	
Witness:		