

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

**HOBBS OGD
AUG 02 2018
RECEIVED**

Operator Name Apache Corp	API Number 30-025-05648
Property Name NMGSAU	Well No. 015 (515)

1. Surface Location

UL - Lot 0	Section 19	Township 19S	Range 37E	Feet from 600	N/S Line S	Feet From 1980	E/W Line E	County Lea
----------------------	----------------------	------------------------	---------------------	-------------------------	----------------------	--------------------------	----------------------	----------------------


Well Status

TA'D WELL YES ☒ NO	SHUT-IN YES ☒ NO	INJECTOR ☒ IN	SWD	PRODUCER OIL	GAS	DATE 8-2-18
--	--	---	-----	-----------------	-----	-----------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	/	0	0	735
Flow Characteristics					
Puff	Y / ☒ N	Y / N	Y / ☒ N	☒ Y / N	CO2 ☐
Steady Flow	Y / ☒ N	Y / N	Y / ☒ N	Y / ☒ N	WTR ☒
Surges	Y / ☒ N	Y / N	Y / ☒ N	Y / ☒ N	GAS ☐
Down to nothing	☒ Y / N	Y / N	☒ Y / N	☒ Y / N	Type of Fluid Injected for Waterflood if applies.
Gas or Oil	Y / ☒ N	Y / N	Y / ☒ N	Y / ☒ N	
Water	Y / ☒ N	Y / N	Y / ☒ N	☒ Y / N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: 	OIL CONSERVATION DIVISION
Printed name: Jim Ellison	Entered into RBDMS
Title: Instrument tech	Re-test 
E-mail Address: JD.Ellison @ apache corp.com	
Date: 8-2-18	Phone: 575-441-7734
Witness:	