

HOBBS OCD
AUG 02 2018
RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Apache Corp	API Number 30-025-05650
Property Name NMGSAU	Well No. 011 (511)

Surface Location

UL - Lot K	Section 19	Township 19S	Range 37E	Feet from 1980	N/S Line S	Feet From 1980	E/W Line W	County Lea
----------------------	----------------------	------------------------	---------------------	--------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status


TA'D WELL YES ☒ NO	SHUT-IN YES ☒ NO	INJECTOR ☒ SWD	PRODUCER OIL ☒ GAS	DATE 8-2-18
--	--	--	--	-----------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	—	10	120	735
Flow Characteristics					
Puff	Y / ☒ N	Y / N	☒ Y / N	☒ Y / N	CO2 —
Steady Flow	Y / ☒ N	Y / N	Y / ☒ N	Y / ☒ N	WTR ☒
Surges	Y / ☒ N	Y / N	Y / ☒ N	Y / ☒ N	GAS —
Down to nothing	☒ Y / N	Y / N	☒ Y / N	☒ Y / N	Type of Fluid Injected for Waterflood if applies.
Gas or Oil	Y / ☒ N	Y / N	☒ Y / N	☒ Y / N	
Water	Y / ☒ N	Y / N	Y / ☒ N	Y / ☒ N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

(b) Bleed down gas to 0 in 15 seconds

Signature: 	OIL CONSERVATION DIVISION
Printed name: Jim Ellison	Entered into RBDMS
Title: Instrument tech	Re-test 
E-mail Address: JD.Ellison @ apache corp.com	
Date: 8-2-18	Phone: 575-441-7734
Witness:	