

HOBBS OCD
AUG 02 2018
RECEIVED

State of New Mexico

Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Apache Corp	* API Number 30-025-05662
Property Name NMGSAU	Well No. 001 (001)

* Surface Location

UL - Lot A	Section 20	Township 19S	Range 37E	Feet from 6600	N/S Line N	Feet From 6600	E/W Line E	County Lea
----------------------	----------------------	------------------------	---------------------	--------------------------	----------------------	--------------------------	----------------------	----------------------



Well Status

TA'D WELL YES ☒ NO	SHUT-IN YES ☒ NO	INJECTOR ☒ SWD	PRODUCER OIL ☒ GAS	DATE 8-2-18
--	--	--	--	-----------------------

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Csg	(E) Tubing
Pressure	0	—	0	20	735
Flow Characteristics					
Puff	Y / ☒ N	Y / N	☒ Y / N	☒ Y / N	CO2 —
Steady Flow	Y / ☒ N	Y / N	Y / ☒ N	Y / ☒ N	WTR ☒
Surges	Y / ☒ N	Y / N	Y / ☒ N	Y / ☒ N	GAS —
Down to nothing	☒ Y / N	Y / N	☒ Y / N	☒ Y / N	Type of Fluid
Gas or Oil	Y / ☒ N	Y / N	☒ Y / N	☒ Y / N	Injected for
Water	Y / ☒ N	Y / N	Y / ☒ N	Y / ☒ N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: 	OIL CONSERVATION DIVISION
Printed name: Jim Ellison	Entered into RBDMS
Title: Instrument Tech	Re-test 
E-mail Address: JD.Ellison @ apache corp.com	
Date:	Phone: 575-441-7734
Witness:	