

HOBBS OGD
AUG 02 2018
RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Apache Corp	API Number 30-025-05721
Property Name NMGSAU	Well No. 002 (1106)

Surface Location

UL - Lot F	Section 29	Township 19S	Range 31E	Feet from 1980	N/S Line N	Feet From 1580	E/W Line J	County Lea
----------------------	----------------------	------------------------	---------------------	--------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status



TA'D WELL YES ☒	SHUT-IN YES ☒	INJECTOR ☒	SWD	PRODUCER OIL	GAS	DATE 8-2-18
---	---	--	-----	-----------------	-----	-----------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	—	0	100	1080
Flow Characteristics					
Puff	Y / ☒	Y / N	☒ / N	☒ / N	CO2 —
Steady Flow	Y / ☒	Y / N	Y / ☒	Y / ☒	WTR ☒
Surges	Y / ☒	Y / N	Y / ☒	Y / ☒	GAS —
Down to nothing	☒ / N	Y / N	☒ / N	☒ / N	Type of Fluid Injected for Waterflood if applies
Gas or Oil	Y / ☒	Y / N	☒ / N	☒ / N	
Water	Y / ☒	Y / N	Y / ☒	Y / ☒	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

(D) Bleed down to 0 in 30 seconds

Signature: 	OIL CONSERVATION DIVISION
Printed name: Jim Ellison	Entered into RBDMS
Title: Instrument tech	Re-test 
E-mail Address: JD.Ellison @ apache corp.com	
Date:	
Phone: 575-441-7734	
Witness:	