

HOBBS OCD
AUG 02 2018
RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Apache Corp	* API Number 30-025-05732
Property Name NMGSAU	Well No. 007 (1107)

1. Surface Location

UL - Lot G	Section 29	Township 19S	Range 37E	Feet from 1980	N/S Line N	Feet From 1980	E/W Line E	County Lea
----------------------	----------------------	------------------------	---------------------	--------------------------	----------------------	--------------------------	----------------------	----------------------



Well Status

TA'D WELL YES ☒	SHUT-IN YES ☒	INJECTOR ☒	SWD	PRODUCER OIL	GAS	DATE 8-2-18
---	---	--	-----	-----------------	-----	-----------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	—	0	20	1080
Flow Characteristics					
Puff	Y / ☒	Y / N	☒ / N	☒ N	CO2 ☐
Steady Flow	Y / ☒	Y / N	Y / ☒	Y / ☒	WTR ☒
Surges	Y / ☒	Y / N	Y / ☒	Y / ☒	GAS ☐
Down to nothing	☒ / N	Y / N	☒ / N	☒ N	Type of Fluid Injected for Waterflood if applies.
Gas or Oil	Y / ☒	Y / N	☒ / N	Y / ☒	
Water	Y / ☒	Y / N	Y / ☒	☒ N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: 	OIL CONSERVATION DIVISION
Printed name: Jim Ellison	Entered into RBDMS
Title: Instrument tech	Re-test 
E-mail Address: JD.Ellison @ apache corp.com	
Date:	
Phone: 575-441-7734	
Witness:	