

HOBBS
AUG 02 2018
RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Apache Corp	* API Number 30-025-05735
Property Name NMGSAU	Well No. 209 (1109)

1. Surface Location

UL - Lot I	Section 29	Township 19S	Range 37E	Feet from 2280	N/S Line S	Feet From 990	E/W Line E	County Lea
----------------------	----------------------	------------------------	---------------------	--------------------------	----------------------	-------------------------	----------------------	----------------------



Well Status

TA'D WELL YES ☒	SHUT-IN YES ☒	INJECTOR ☒	PRODUCER OIL ☒	GAS ☐	DATE 8-2-18
---	---	--	--	---------------------------	-----------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0			0	1080
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 ☐
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ☒
Surges	Y / N	Y / N	Y / N	Y / N	GAS ☐
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: 	OIL CONSERVATION DIVISION
Printed name: Jim Ellison	Entered into RBDMS
Title: Instrument tech	Re-test 
E-mail Address: JD.Ellison @ apache corp.com	
Date:	Phone: 575-441-7734
Witness:	