

HOBBS OCD
AUG 02 2018
RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Apache Corp	API Number 30-025-05738
Property Name NMGSAU	Well No. 001 (101)

Surface Location

UL Lot A	Section 29	Township 19S	Range 37E	Feet from 660	N/S Line N	Feet From 660	E/W Line E	County Lea
--------------------	----------------------	------------------------	---------------------	-------------------------	----------------------	-------------------------	----------------------	----------------------

Well Status



TA'D WELL YES	SHUT-IN NO	INJECTOR NO	SWD NO	PRODUCER OIL	GAS NO	DATE 8-2-18
-------------------------	----------------------	-----------------------	------------------	------------------------	------------------	-----------------------

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Casing	(E) Tubing
Pressure	0	✓	0	120	1080
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 —
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ✓
Surges	Y / N	Y / N	Y / N	Y / N	GAS —
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

(D) Bled to 0 in 15 seconds to 9 trickle for 9 minutes to no flow

Signature: 	OIL CONSERVATION DIVISION	
Printed name: Jim Ellison	Entered into RBDMS	
Title: Instrument tech	Re-test 	
E-mail Address: JD.Ellison @ apache corp.com		
Date:	Phone: 575-441-7734	
Witness:		