

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Apache Corp		* API Number 30-025-05724	
Property Name NMGSAU		Well No. 113 (115)	

7. Surface Location

UL - Lot M	Section 29	Township 19S	Range 37E	Feet from 660	N/S Line S	Feet From 660	E/W Line W	County Lea
----------------------	----------------------	------------------------	---------------------	-------------------------	----------------------	-------------------------	----------------------	----------------------



Well Status

TA'D WELL YES ☐ NO ☒	SHUT-IN YES ☐ NO ☒	INJECTOR ☒	SWD	OIL	PRODUCER GAS	DATE 8-2-18
--	--	--	-----	-----	-----------------	-----------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0		0	0	1080
Flow Characteristics					
Puff	Y / ☒ N	Y / N	☒ Y / N	☒ Y / N	CO2 ☐
Steady Flow	Y / ☒ N	Y / N	Y / ☒ N	Y / ☒ N	WTR ☒
Surges	Y / ☒ N	Y / N	Y / ☒ N	Y / ☒ N	GAS ☐
Down to nothing	☒ Y / N	Y / N	☒ Y / N	☒ Y / N	Type of Fluid Injected for Waterflood if applies
Gas or Oil	Y / ☒ N	Y / N	Y / ☒ N	Y / ☒ N	
Water	Y / ☒ N	Y / N	☒ Y / N	☒ Y / N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: 		OIL CONSERVATION DIVISION	
Printed name: Jim Ellison		Entered into RBDMS	
Title: Instrument tech		Re-test 	
E-mail Address: JD.Ellison @ apache corp.com			
Date:	Phone: 575-441-7734		
Witness:			