

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Sundown Energy LP		API Number 30-025-27586
Property Name Bobbi St. Waterflood Unit		Well No. 4

7. Surface Location

UL - Lot 2	Section 20	Township 18S	Range 36E	Feet from 1650	N/S Line S	Feet From 990	E/W Line W	County Lea
----------------------	----------------------	------------------------	---------------------	--------------------------	----------------------	-------------------------	----------------------	----------------------

Well Status

TA/D Well YES ☒ NO ☒	SHUT-IN YES ☒ NO ☒	INJECTOR INJ ☒ SWD ☐	PRODUCER OIL ☐ GAS ☐	DATE 7/18/18
---	---	--	---	------------------------

OBSERVED DATA

	(A)Surf-Interm	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	N/A	—	—	φ	1200
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 _____
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR _____
Surges	Y / N	Y / N	Y / N	Y / N	GAS _____
Down to nothing	Y / N	Y / N	Y / N	Y / N	If applicable type
Gas or Oil	Y / N	Y / N	Y / N	Y / N	fluid injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: Belinda Bradley		OIL CONSERVATION DIVISION
Printed name: Belinda Bradley		Entered into RBDMS
Title: Production Asst.		Re-test
E-mail Address: bbradley@sundownenergy.com		[Signature]
Date: 7/18/18	Phone: 432-943-8770	
Witness: [Signature]		