

HOBBS OCD
RECEIVED
JUL 27 2018

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Sundown Energy LP	API Number 30-025-29526
Property Name Reeves Queen Waterflood Unit	Well No. 2

7. Surface Location

U/L Lot B	Section 28	Township 18S	Range 35E	Feet from 330	N/S Line N	Feet From 1650	E/W Line E	County Lea
---------------------	----------------------	------------------------	---------------------	-------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

TA'D Well YES ☐ NO ☒	SHUT-IN YES ☐ NO ☒	INJECTOR INJ ☒ SWD ☐	PRODUCER OIL ☐ GAS ☐	DATE 7/18/18
--	--	--	---	------------------------

OBSERVED DATA

	(A)Surf-Interm	(B)Interm(1)	(C)Interm(2)	(D)Prod Csng	(E)Tubing
Pressure	n/a	—	—	φ	1150
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / ☒ N	CO2 ☐
Steady Flow	Y / N	Y / N	Y / N	Y / ☒ N	WTR ☐
Surges	Y / N	Y / N	Y / N	Y / ☒ N	GAS ☐
Down to nothing	Y / N	Y / N	Y / N	☒ Y / N	If applicable type
Gas or Oil	Y / N	Y / N	Y / N	Y / ☒ N	fluid injected for
Water	Y / N	Y / N	Y / N	Y / ☒ N	Waterflood

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: Belinda Bradley	OIL CONSERVATION DIVISION
Printed name: Belinda Bradley	Entered into RBDMS
Title: Production Asst.	Re-test
E-mail Address: bbradley@sundownenergy.com	
Date: 7/18/18	Phone: 432-943-8770
Witness: [Signature]	