

HOBBES OCD
AUG 06 2018
RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Apache Oil Corp.		API Number 30-025-06465	
Property Name North East Drinkard Unit		Well No. 506	

1. Surface Location

UL - Lot 0	Section 10	Township 21S	Range 37E	Feet from 660	N/S Line S	Feet From 1980	E/W Line E	County Lea
----------------------	----------------------	------------------------	---------------------	-------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

YES ☒ TA'D WELL	YES ☒ SHUT-IN	YES ☒ INJECTOR	YES ☐ SWD	YES ☐ PRODUCER	YES ☐ GAS	DATE 8/5/18
---	---	--	----------------------------------	---------------------------------------	----------------------------------	-----------------------

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Case	(E) Tubing
Pressure	0	-	-	1100	1100
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	SO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid Injected for Wellhead V applies
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Tubing is communicating with prod. case, press. is equilized.
Shut well in, and put on, needs repair list.
Failure - Record only

Signature: Tracy Cole		OIL CONSERVATION DIVISION	
Printed name: Tracy Cole		Entered into RBDMS	
Title:		Re-test	
E-mail Address:			
Date: 8/5/18	Phone: 575-441-5196		
Witness:			