

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name: Apache Oil Corp. APT Number: 30-025-06727
Property Name: Northeast Drinkard Unit Well No.: 806

Surface Location

UL - Lot	Section	Township	Range	Feet from	N/S Line	Feet From	E/W Line	County
<u>B</u>	<u>22</u>	<u>21S</u>	<u>37E</u>	<u>660</u>	<u>N</u>	<u>1780</u>	<u>E</u>	<u>Lea</u>

Well Status

TA'D WELL YES ☒	SHUT-IN YES ☒	INJECTOR ☒	SWD ☐	PRODUCER OIL ☐	GAS ☐	DATE <u>6/21/18</u>
--	--	---	---------------------------------	--	---------------------------------	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	<u>Ø</u>	<u>—</u>	<u>—</u>	<u>Ø</u>	<u>1000</u>
Flow Characteristics					
Puff	Y / ☒ N	Y / N	Y / N	☒ Y / N	CO2 <u>—</u>
Steady Flow	Y / ☒ N	Y / N	Y / N	Y / ☒ N	WTR <u>—</u>
Surges	Y / ☒ N	Y / N	Y / N	Y / ☒ N	GAS <u>—</u>
Down to nothing	Y / N	Y / N	Y / N	☒ Y / N	Type of fluid injected for water flow if applies
Gas or Oil	Y / ☒ N	Y / N	Y / N	Y / ☒ N	
Water	Y / ☒ N	Y / N	Y / N	Y / ☒ N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: <u>Tracy Cole</u>	OIL CONSERVATION DIVISION
Printed name: <u>Tracy Cole</u>	Entered into RBDMS
Title: <u>Pumper III</u>	Re-test
E-mail Address: <u>Tracy.Cole@apachecorp.com</u>	
Date: <u>6/21/18</u>	Phone: <u>575-441-5196</u>
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM