

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

HOBBS OCD
AUG 10 2018
RECEIVED

Operator Name Apache Corp	API Number 30-025-05744
Property Name NMGSAU	Well No. 023 (1003)

Surface Location

UL - Lot C	Section 30	Township 19S	Range 37E	Feet from 660	N/S Line N	Feet From 190	E/W Line W	County Lea
----------------------	----------------------	------------------------	---------------------	-------------------------	----------------------	-------------------------	----------------------	----------------------



Well Status

TA'D WELL YES	SHUT-IN NO	INJECTOR NO	SWD NO	OIL PRODUCER YES	GAS NO	DATE 8-9-18
-------------------------	----------------------	-----------------------	------------------	----------------------------	------------------	-----------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	2	0	0	0	740
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 ☐
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ☒
Surges	Y / N	Y / N	Y / N	Y / N	GAS ☐
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid Injected for Waterflood if applies.
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: 	OIL CONSERVATION DIVISION
Printed name: Jim Ellison	Entered into RBDMS
Title: Instrument tech	Re-test 
E-mail Address: JD.Ellison @ apache corp.com	
Date:	Phone: 575-441-7734
Witness:	