

**HOBBS OIL
AUG 10 2018
RECEIVED**

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Apache Corp	API Number 30-025-05754
Property Name NMGSAU	Well No. 009 (1009)

Surface Location

UL - Lot 17	Section 30	Township 19S	Range 37E	Feet from 1980	N/S Line S	Feet From 660	F/V Line E	County Lea
-----------------------	----------------------	------------------------	---------------------	--------------------------	----------------------	-------------------------	----------------------	----------------------



Well Status

TA'D WELL YES ☒ NO ☒	SHUT-IN YES ☒ NO ☒	INJECTOR ☒	SWD	OIL	PRODUCER	GAS	DATE 8-9-18
---	---	---	-----	-----	----------	-----	-----------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	0		10	1090
<u>Flow Characteristics</u>					
Puff	Y / N	Y / N	Y / N	☒ N	CO2 ☐
Steady Flow	Y / N	Y / N	Y / N	Y / ☒	WTR ☒
Surges	Y / N	Y / N	Y / N	Y / ☒	GAS ☐
Down to nothing	Y / N	Y / N	Y / N	☒ N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / ☒	Injected for
Water	Y / N	Y / N	Y / N	☒ N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: 		OIL CONSERVATION DIVISION	
Printed name: Jim Ellison		Entered into RBDMS	
Title: Instrument Tech		Re-test 	
E-mail Address: JD.Ellison @ apache corp.com			
Date:	Phone: 575-441-7734		
Witness:			