

HOBBS OCD

AUG 10 2018

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

RECEIVED	Operator Name <i>Apache Corp</i>	* API Number <i>30-025-29771</i>
	Property Name <i>NMGSAU</i>	Well No. <i>009 (409)</i>

1. Surface Location									
UL - Lot <i>I</i>	Section <i>24</i>	Township <i>19S</i>	Range <i>36E</i>		Feet from <i>1654</i>	N/S Line <i>S</i>	Feet From <i>330</i>	E/W Line <i>E</i>	County <i>Lea</i>

Well Status									
TA'D WELL YES ☒	SHUT-IN YES ☒	INJECTOR ☒	SWD	OIL	PRODUCER	GAS	DATE <i>8-9-18</i>		

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	<i>2</i>	<i>-</i>	<i>-</i>	<i>2</i>	<i>740</i>
<u>Flow Characteristics</u>					
Puff	Y / N	Y / N	Y / N	☒ Y / N	CO2 ☐
Steady Flow	Y / N	Y / N	Y / N	Y / ☒ N	WTR ☒
Surges	Y / N	Y / N	Y / N	Y / ☒ N	GAS ☐
Down to nothing	Y / N	Y / N	Y / N	☒ Y / N	Type of Fluid Injected for Waterflood if applies
Gas or Oil	Y / N	Y / N	Y / N	Y / ☒ N	
Water	Y / N	Y / N	Y / N	☒ Y / N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: <i>JD Ellison</i>	OIL CONSERVATION DIVISION
Printed name: <i>Jim Ellison</i>	Entered into RBDMS
Title: <i>Instrument tech</i>	Re-test <i>[Signature]</i>
E-mail Address: <i>JD.Ellison @ apache corp.com</i>	
Date:	Phone: <i>575-441-7734</i>
Witness:	