

HOBBS OCD State of New Mexico
Energy, Minerals and Natural Resources Department
AUG 10 2018 Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

RECEIVED		API Number	
COG Operating		30-025-39519 ✓	
Property Name		Well No.	
Maljamar SWD 29		#1 ✓	

7. Surface Location									
UL - Lot	Section	Township	Range		Feet from	N/S Line	Feet From	E/W Line	County
0	29	17S	32E		490	5	2160	E	LETA ✓

Well Status											
TA'D WELL	YES	NO	SHUT-IN	YES	NO	INJECTOR	SWD	PRODUCER	OIL	GAS	DATE
											7-25-18 ✓

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	N/A	N/A	0	1340 ✓
Flow Characteristics					
Pull	Y/N	Y/N	Y/N	Y/N	CO2 —
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR ✓
Surges	Y/N	Y/N	Y/N	Y/N	GAS —
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood if
					applies

Remarks – Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: <i>Hilaris J. Jener</i>		OIL CONSERVATION DIVISION	
Printed name: <i>Hilaris J. Jener</i>		Entered into RBDMS	
Title: <i>SWD Foreman</i>		Re-test	
E-mail Address: <i>HJener@concho.com</i>			
Date: <i>7-26-2018</i>	Phone: <i>432-246-5191</i>		
Witness: <i>Dany Robinson</i>			

INSTRUCTIONS ON BACK OF THIS FORM