

Submit 1 Copy To Appropriate District Office
 District I - (575) 393-6161
 1625 N. French Dr., Hobbs, NM 88240
 District II - (575) 748-1283
 811 S. First St., Artesia, NM 88210
 District III - (505) 334-6178
 1000 Rio Brazos Rd., Aztec, NM 87410
 District IV - (505) 476-3460
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
 Energy, Minerals and Natural Resources

Form C-103
 Revised July 18, 2013

OIL CONSERVATION DIVISION
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-26752 ✓
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/> HOBBS OCD ✓		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/> ✓
2. Name of Operator RMR Operating, LLC		6. State Oil & Gas Lease No.
3. Address of Operator 14282 Gillis Rd, Farmers Branch, TX 75244		7. Lease Name or Unit Agreement Name Maralo 16 State ✓
4. Well Location Unit Letter K : 1980 feet from the South line and 1980 feet from the West line Section 16 Township 26-S Range 36-E NMPM County Lea ✓		8. Well Number 8 ✓
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 2943' GL		9. OGRID Number 281085 ✓
RECEIVED		10. Pool name or Wildcat Sioux, Tansill-Yates-Seven Rivers ✓

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO PLUG PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> DOWNHOLE COMMINGLE <input type="checkbox"/> CLOSED-LOOP SYSTEM <input type="checkbox"/> OTHER: _____	INT TO P&A P&A NR <u>PM</u> P&A R _____	SUBSEQUENT REPORT OF: REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> P AND A <input checked="" type="checkbox"/> CASING/CEMENT JOB <input type="checkbox"/> OTHER: _____ <input type="checkbox"/>
---	--	--

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

See Attachment

Approved for Plugging of wellbore only. Liability under bond is retained pending restoration and completion of the C-103, Specific for Subsequent report of Well Plugging, which may be found on the OCD web page under forms.
 Restoration Due By **7-3-2019**

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Alan W Barksdale TITLE President DATE 8/17/18

Type or print name Alan W Barksdale E-mail address: alan@redmountainresources.com PHONE: 501-412-4097
 For State Use Only

APPROVED BY: Manuel P. E. S. TITLE P.E.S. DATE 08/20/2018

Conditions of Approval (if any):

✓

MARALO 16 STATE #8 (LEA COUNTY, NEW MEXICO)

07/01/18	RODE EQUIP TO LOC – HELD TAILGATE SAFETY MEETING & JSA ON RU. CLEARED LOC, SET STEEL MAT & RU. OPEN WELL – NO PRESS. UNBOLTED FLANGE FROM WH & NU BOP. CYCLE TESTED BOP – TESTED GOOD. MI REMAINING EQUIP. POOH W/ 98 JTS 2-3/8” TBG & VERIFIED THERE WERE NO HOLES. RIH TO 3,120’. DUG OUT CELLAR & CHANGED OUT VALVES. CWI. SDFN.
07/02/18	ARRIVED ON LOC – HELD TAILGATE SAFETY MEETING & JSA ON PERF & SQZ. OPEN WELL – NO PRESS. CIRC HOLE W/ MLF & SPOTTED 30 SXS CMT ON TOP OF CIBP @ 3,100’. POOH TO 2,045’ & SPOTTED 25 SXS CMT. POOH & WOC. RIH & TAGGED TOC @ 1,700’. POOH. RU SLICKLINE, RIH & PERF @ 1,474’. POOH & RD SLICKLINE. RIH W/ TBG & EST. PUMP IN RATE. SQZ 50 SXS CMT. POOH & WOC. WELL NEVER CIRCULATED OUT SURF. CWI. SDFN. WILL ATTEMPT TO TAG PLUG TOMORROW AM.
07/03/18	ARRIVED ON LOC – HELD TAILGATE SAFETY MEETING & JSA ON TRIPS & FALLS. OPEN WELL – NO PRESS. RIH & TAGGED TOC @ 1,345’. POOH TO 722’ & PERF. POOH & RD SLICKLINE. RIH W/ TBG & SQZ 50 SXS CMT. POOH & WOC. RIH & TAGGED TOC @ 605’. POOH W/ TBG. RU SLICKLINE, RIH & PERF @ 200’. POOH & RD SLICKLINE. INSTALLED WH FLANGE & SQZ 70 SXS CMT @ 300# – NEVER CIRCULATED @ SURF OR SHOWED ANY SIGNS OF SQZ. CWI. SDFN.
07/04/18	SDF HOLIDAY
07/05/18	ARRIVED ON LOC – HELD TAILGATE SAFETY MEETING & JSA. OPEN WELL – NO PRESS. DUG OUT CELLAR. CHECKED FOR GAS & CUT OFF WH. PUMPED THP. CAPPED WELL & COVERED CELLAR. RD TRUCKS & MOVED OFF LOC. RD RIG, LOADED BEAM TRAILER & MO. WELL COMPLETE.