

HOBBS OCD

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

AUG 21 2018

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Bridwell Oil Co.						API Number 30-025-24264			
Property Name New Mexico 8 ST.						Well No. #3			
1. Surface Location									
UL Lot F	Section 8	Township 9S	Range 33E	Feet from 1980	N/S Line N	Feet from 1980	E/W Line W	County LEA	

Well Status

TA'D WELL YES ☐ NO ☒	SHUT-IN YES ☐ NO ☒	INJ ☐	INJECTOR ☒ SWD	OIL PRODUCER ☐	GAS ☐	DATE 8-21-18
--	--	------------------------------	--	---------------------------------------	------------------------------	------------------------

OBSERVED DATA

	(A) Surface	(B) Intern(1)	(C) Intern(2)	(D) Prod Csg	(E) Tubing
Pressure	0	N/A	N/A		160
Flow Characteristics					
Pull	Y / N	Y / N	Y / N	Y / N	CO2 ☐
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ☒
Surges	Y / N	Y / N	Y / N	Y / N	GAS ☐
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid Injected for Waterflood if applies.
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

Well was shut in

Remarks - Please state for each string (A, B, C, D, E) pertinent information regarding blockages or continuous build up if applies.

*Started to ~~bleed~~ bleed prod. csg, down + it went to
oil - called truck + blew into truck - blew to
ZERO - Turned SWD pump on + water started flowing out of Prod.
csg.
Failed BHT Rule: 19.15.26.11
C-103 - Int end of what's going to be done.
C-103 - After repairs of wellbore dis...*

Signature: Mike Malone	325-668-0339	OIL CONSERVATION DIVISION
Printed name: Mike Malone	Entered into RBDMS	
Title:	Re-test	
E-mail Address:		
Date:	Phone:	
	Witness: Harry Robinson	

INSTRUCTIONS ON BACK OF THIS FORM