

AUG 23 2018

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name MATADOR PRODUCTION COMPANY		API Number 30-025-26547-0000
Property Name ANTELOPE RIDGE 24 SWD		Well No. 001

7. Surface Location

UL - Lot K	Section 24	Township 23-S	Range 34-E	Feet from 1980	N/S Line S	Feet From 1980	E/W Line W	County LEA
----------------------	----------------------	-------------------------	----------------------	--------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

TA'D Well YES NO	SHUT-IN YES NO	INJECTOR INJ SWD	PRODUCER OIL GAS	DATE 8/23/18
----------------------------	--------------------------	----------------------------	----------------------------	------------------------

OBSERVED DATA

	(A)Surf-Interm	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure				0	725
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / 0	CO2 —
Steady Flow	Y / N	Y / N	Y / N	Y / 0	WTR —
Surges	Y / N	Y / N	Y / N	Y / 0	GAS —
Down to nothing	Y / N	Y / N	Y / N	0 / N	If applicable type
Gas or Oil	Y / N	Y / N	Y / N	Y / 0	fluid injected for
Water	Y / N	Y / N	Y / N	Y / 0	Waterflood

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: Dore Regan		OIL CONSERVATION DIVISION	
Printed name:		Entered into RBDMS	
Title:		Re-test KJ	
E-mail Address:			
Date: 8/23/18	Phone:		
Witness: KERRY FORTNER-OCD 575-399-3221			