

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED
AUG 30 2018
HOBBS OGD

BRADENHEAD TEST REPORT

Operator Name DEVON ENERGY	API Number 3002534702
Property Name Corbin	Well No. South Shoebar 15 State 2

7. Surface Location

30-025-34702

UL - Lot H	Section 15	Township 17S	Range 35E	Feet from 1650	N/S Line N	Feet From 800	E/W Line E	County Lea
---------------	---------------	-----------------	--------------	-------------------	---------------	------------------	---------------	---------------

Well Status

TA'D Well YES NO	SHUT-IN YES NO	INJECTOR INJ SWD	PRODUCER OIL GAS	DATE 8-27-18
---------------------	-------------------	---------------------	---------------------	-----------------

OBSERVED DATA

	(A)Surf-Interm	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	0		0	0
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 _____
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR _____
Surges	Y / N	Y / N	Y / N	Y / N	GAS _____
Down to nothing	Y / N	Y / N	Y / N	Y / N	If applicable type
Gas or Oil	Y / N	Y / N	Y / N	Y / N	fluid injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood

If bradenhead flowed water, check all of the descriptions that apply:

--	--	--	--

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

- A. Light puff no pressure or flow.
- B. Light puff no pressure or flow.

Signature: Ray Carter	OIL CONSERVATION DIVISION
Printed name: Ray Carter	Entered into RBDMS
Title: Assistant Foreman	Re-test
E-mail Add ray.carter@dv.com	
Date: 8/27/18	Phone: 575 513 0956
Witness:	