

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

AUG 31 2018

RECEIVED

BRADENHEAD TEST REPORT

Operator Name HAISER- FRANCIS	API Number 30-025-10448
Property Name Dang/ADC	Well No. 1

7. Surface Location

UL - Lot 18	Section 24	Township 22S	Range 37E	Feet from 660	N/S Line N	Feet From 1980	E/W Line E	County Lea
-----------------------	----------------------	------------------------	---------------------	-------------------------	----------------------	--------------------------	----------------------	----------------------




Well Status

TA'D WELL YES ☐ NO ☒	SHUT-IN YES ☒ NO ☐	INJECTOR INJ ☐ SWD ☐	PRODUCER OIL ☒ GAS ☐	DATE 8/31/18
--	--	---	---	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod C'sng	(E)Tubing
Pressure	0	—	—	20	20
Flow Characteristics					
Pull	Y/N	Y/N	Y/N	Y/N	CO2 ☐
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR ☐
Surges	Y/N	Y/N	Y/N	Y/N	GAS ☐
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid Injected for Waterflood if applies
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: 	OIL CONSERVATION DIVISION
Printed name: John P. Bower	Entered into RBDMS
Title:	Re-test 
E-mail Address:	
Date: 8/31/18	Phone:
Witness: 	

INSTRUCTIONS ON BACK OF THIS FORM