

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

HOBBS OCD

SEP 04 2018

BRADENHEAD TEST REPORT

RECEIVED

Operator Name Devon Energy		API Number 30-025-33653
Property Name Diamond Tail 23 Fed.		Well No. #2

Surface Location

UL - Lot H	Section 23	Township 23S	Range 32E	Feet from 1980	N/S Line N	Feet from 660	E/W Line E	County LEA
----------------------	----------------------	------------------------	---------------------	--------------------------	----------------------	-------------------------	----------------------	----------------------

Well Status


TA'D WELL YES ☒ NO	SHUT-IN YES ☒ NO	INJ INJ ☒ SWD	OIL OIL ☒ GAS	DATE 9-4-18
--	--	---	---	-----------------------

OBSERVED DATA

	(A) Surface	(B) Intern#1	(C) Intern#2	(D) Prod Csg	(E) Tubing
Pressure	0		N/A	0	29
Flow Characteristics		0		0	
Pull	Y	Y	Y / N	Y	CO2 ☒
Steady Flow	Y	Y	Y / N	Y	WTR ☒
Surges	Y	Y	Y / N	Y	GAS ☒
Down to nothing	Y	Y	Y / N	Y	Type of fluid injected for water flood if applies
Gas or Oil	Y	Y	Y / N	Y	
Water	Y	Y	Y / N	Y	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Pump down - Maintenance

Signature: 	OIL CONSERVATION DIVISION
Printed name:	Entered into RBDMS
Title:	Re-test
E-mail Address:	
Date:	
Phone:	
Witness: Gay Kolman	

INSTRUCTIONS ON BACK OF THIS FORM