

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name ARMSTRONG ENERGY		API Number 30-025-33843
Property Name HOOVER 32		Well No. 4

7. Surface Location

UL - Lot J	Section 32	Township 17	Range 35E	Feet from 2060	N/S Line S	Feet From 1760	E/W Line E	County LEA
---------------	---------------	----------------	--------------	-------------------	---------------	-------------------	---------------	---------------

Well Status

TA'D Well YES ☒ NO	SHUT-IN YES ☒ NO	INJECTOR INJ SWD	PRODUCER OIL GAS	DATE 3/2/18
--	--	---------------------	---------------------	----------------

OBSERVED DATA

	(A)Surf-Interm	(B)Interm(1)	(C)Interm(2)	(D)Prod C/sng	(E)Tubing
Pressure	0	N/A	N/A		
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 _____
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR _____
Surges	Y / N	Y / N	Y / N	Y / N	GAS _____
Down to nothing	Y / N	Y / N	Y / N	Y / N	If applicable type
Gas or Oil	Y / N	Y / N	Y / N	Y / N	fluid injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood


If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

FAILURE- GAS & OIL ON SURFACE. RULE:19.15.26.11

Failure
Plugging Gms

Signature: 	OIL CONSERVATION DIVISION
Printed name: Kyle Alpers	Entered into RBDMS
Title: VP Operations	Re-test
E-mail Address: kalpers@aeconm.com	
Date: 3/2/18	Phone: 575 625 2222
Witness: GEORGE BOWER	