

HOBBS OCD
AUG 30 2018
RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Apache	API Number 30-025-06434
Property Name WBDU	Well No. 41

1. Surface Location

UL - Lot 1	Section 8	Township 21S	Range 37E	Feet from 1980	N/S Line S	Feet from 6660	E/W Line E	County Lea
----------------------	---------------------	------------------------	---------------------	--------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

TA'D WELL YES ☒ NO ☒	SHUT-IN YES ☒ NO ☒	INJECTOR ☒	SWD	PRODUCER OIL	GAS	DATE 6-22-18
---	---	--	-----	-----------------	-----	------------------------

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Casing	(E) Tubing
Pressure	0	0		0	0
Flow Characteristics					Vac
Puff	Y/N	Y/N	Y/N	Y/N	CO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	WIR ☒
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid Inferred for Water Based if applies
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: [Signature]	OIL CONSERVATION DIVISION
Printed name: Russell Pickrel	Entered into RBDMS
Title: Pumper	Re-test
E-mail Address:	[Signature]
Date:	
Phone: 575-942-8435	
Witness: X	