

HOBBS OCD

AUG 24 2018

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Apache Corp	API Number 30-025-24164
Property Name NMGSAU	Well No. 209 (1309)

Surface Location

UL - Lot 1	Section 2	Township 20S	Range 36E	Feet from 1980	N/S Line S	Feet from 660	E/W Line E	County Lea
----------------------	---------------------	------------------------	---------------------	--------------------------	----------------------	-------------------------	----------------------	----------------------


Well Status

TA'D WELL YES ☒ NO ☐	SHUT-IN YES ☐ NO ☒	INJECTOR ☒	SWD	OIL PRODUCER GAS	DATE 8-23-18
--	--	---	-----	---------------------	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure	0	0		0	720
Flow Characteristics					
Puff	Y/N ☒	Y/N ☒	Y/N	Y/N ☒	CO2 ☐
Steady Flow	Y/N ☒	Y/N ☒	Y/N	Y/N ☒	WTR ☒
Surges	Y/N ☒	Y/N ☒	Y/N	Y/N ☒	GAS ☐
Down to nothing	Y/N ☒	Y/N ☒	Y/N	Y/N ☒	Type of Fluid Injected for Waterflood if applies.
Gas or Oil	Y/N ☒	Y/N ☒	Y/N	Y/N ☒	
Water	Y/N ☒	Y/N ☒	Y/N	Y/N ☒	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: 	OIL CONSERVATION DIVISION
Printed name: Jim Ellison	Entered into RBDMS
Title: Instrument tech	Re-test
E-mail Address: JD.Ellison @ apache corp.com	
Date:	
Phone: 575-441-7734	
Witness:	