

HOBBS OCD

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

AUG 24 2018

BRADENHEAD TEST REPORT

RECEIVED

Operator Name Apache Corp		API Number 30-025-04168	
Property Name NMGSAU		Well No. 027 (1807)	

Surface Location

UL Lot 6	Section 2	Township 20S	Range 36E	Feet from 1980	N/S Line N	Feet From 1980	E/W Line E	County Lea
--------------------	---------------------	------------------------	---------------------	--------------------------	----------------------	--------------------------	----------------------	----------------------



Well Status

TA'D WELL YES <input checked="" type="radio"/>	SHUT-IN YES <input checked="" type="radio"/>	INJECTOR <input checked="" type="radio"/>	PRODUCER OIL <input checked="" type="radio"/>	GAS <input type="radio"/>	DATE 8-23-18
---	---	--	--	---------------------------	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	0		0	125
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 <input type="checkbox"/>
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR <input checked="" type="checkbox"/>
Surges	Y/N	Y/N	Y/N	Y/N	GAS <input type="checkbox"/>
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Injected for
Water	Y/N	Y/N	Y/N	Y/N	Water Used if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: 		OIL CONSERVATION DIVISION	
Printed name: Jim Ellison		Entered into RBDMS	
Title: Instrument tech		Re-test 	
E-mail Address: JD.Ellison @ apache corp.com			
Date:	Phone: 575-441-7734		
Witness:			