

AUG 24 2018

RECEIVED

State of New Mexico
 Energy, Minerals and Natural Resources Department
 Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Apache Corp	API Number 30-025-05789
Property Name NMGSAU	Well No. 015 (165)

Surface Location

UL - Lot 0	Section 32	Township 19S	Range 37E	Feet from 660	N/S Line S	Feet From 1980	E/W Line E	County Lea
----------------------	----------------------	------------------------	---------------------	-------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

TA'D WELL YES <input checked="" type="checkbox"/>	SHUT-IN YES <input checked="" type="checkbox"/>	INJECTOR <input checked="" type="checkbox"/>	SWD <input type="checkbox"/>	PRODUCER OIL <input checked="" type="checkbox"/>	GAS <input type="checkbox"/>	DATE 8-23-18
--	--	---	---------------------------------	---	---------------------------------	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	0		10	1090
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 <input type="checkbox"/>
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR <input checked="" type="checkbox"/>
Surges	Y/N	Y/N	Y/N	Y/N	GAS <input type="checkbox"/>
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid Injected for Waterflood if applies.
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: 	OIL CONSERVATION DIVISION
Printed name: Jim Ellison	Entered into RBDMS
Title: Instrument tech	Re-test
E-mail Address: JD.Ellison @ apache corp.com	
Date:	Phone: 575-441-7734
Witness:	