

HOBBS OCD

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

AUG 24 2018

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Apache Corp	* API Number 30-025-05796
Property Name NMGSAU	Well No. 012 (142)

1. Surface Location

UL - Lot L	Section 32	Township 19S	Range 37E	Feet from 1980	N/S Line S	Feet From 660	E/W Line W	County Lea
----------------------	----------------------	------------------------	---------------------	--------------------------	----------------------	-------------------------	----------------------	----------------------



Well Status

TA'D WELL YES ☒	SHUT-IN YES ☒	INJECTOR ☒	SWD	PRODUCER OIL	GAS	DATE 8-23-18
---	---	--	-----	-----------------	-----	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	0		0	1090
Flow Characteristics					
Puff	Y / ☒	☒ N	Y / N	Y / ☒	CO2 ☐
Steady Flow	Y / ☒	Y / ☒	Y / N	Y / ☒	WTR ☒
Surges	Y / ☒	Y / ☒	Y / N	Y / ☒	GAS ☐
Down to nothing	☒ N	☒ N	Y / N	☒ N	Type of Fluid Injected for Waterflood if applies
Gas or Oil	Y / ☒	☒ N	Y / N	Y / ☒	
Water	Y / ☒	Y / ☒	Y / N	Y / ☒	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: 	OIL CONSERVATION DIVISION
Printed name: Jim Ellison	Entered into RBDMS
Title: Instrument tech	Re-test 
E-mail Address: JD.Ellison @ apache corp.com	
Date:	Phone: 575-441-7734
Witness:	