

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

HOBBS OCD

AUG 24 2018

BRADENHEAD TEST REPORT

RECEIVED

Operator Name Apache Corp	* API Number 30-025-05910
Property Name NMGSAU	Well No. 024 (2104)

2. Surface Location

UL - Lot D	Section 5	Township 20S	Range 37E	Feet from 660	N/S Line N	Feet From 660	E/W Line N	County Lea
----------------------	---------------------	------------------------	---------------------	-------------------------	----------------------	-------------------------	----------------------	----------------------


Well Status

TA'D WELL YES ☒	SHUT-IN YES ☒	INJECTOR ☒	SWD	OIL	PRODUCER GAS	DATE 8-23-18
---	---	--	-----	-----	-----------------	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0			0	1090
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 ☐
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR ☒
Surges	Y/N	Y/N	Y/N	Y/N	GAS ☐
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid Injected for Water-flood if applies.
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: 	OIL CONSERVATION DIVISION
Printed name: Jim Ellison	Entered into RBDMS
Title: Instrument tech	Re-test 
E-mail Address: JD.Ellison @ apache corp.com	
Date:	Phone: 575-441-7734
Witness:	