

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

HOBBS OCD

AUG 24 2018

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Apache Corp		API Number 30-025-12466	
Property Name NMGSAU		Well No. 202 (1402)	

7. Surface Location

UL - Lot 13	Section 36	Township 19S	Range 36E	Feet from 660	N/S Line N	Feet from 1980	E/W Line E	County Lea
-----------------------	----------------------	------------------------	---------------------	-------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

TA'D WELL YES ☒	SHUT-IN YES ☒	INJECTOR ☒	SWD	OIL	PRODUCER GAS	DATE 8-23-18
--	--	---	-----	-----	-----------------	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	0		0	725
Flow Characteristics					
Puff	Y / ☒ N	☒ Y / N	Y / N	☒ Y / N	CO2 ☒
Steady Flow	Y / ☒ N	Y / ☒ N	Y / N	Y / ☒ N	WTR ☒
Surges	Y / ☒ N	Y / ☒ N	Y / N	Y / ☒ N	GAS ☒
Down to nothing	☒ Y / N	☒ Y / N	Y / N	☒ Y / N	Type of Fluid Injected for Waterflood if applies
Gas or Oil	Y / ☒ N	☒ Y / N	Y / N	☒ Y / N	
Water	Y / ☒ N	Y / ☒ N	Y / N	Y / ☒ N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: JD Ellison		OIL CONSERVATION DIVISION	
Printed name: Jim Ellison		Entered into RBDMS	
Title: Instrument tech		Re-test	
E-mail Address: JD.Ellison @ apache corp.com		JD	
Date:	Phone: 575-441-7734		
Witness:			