

SEP 18 2018

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Mesquite SWD		API Number 30-025-27616	
Property Name Padoca SWD		Well No. #1	

Surface Location

UL - Lot H	Section 22	Township 25S	Range 32E	Feet from 1980	N/S Line N	Feet from 660	E/W Line E	County LEA
----------------------	----------------------	------------------------	---------------------	--------------------------	----------------------	-------------------------	----------------------	----------------------

Well Status

TA'D WELL YES ☐ NO ☒	SHUT-IN YES ☐ NO ☒	INJECTOR INJ ☐ SWD ☒	PRODUCER OIL ☐ GAS ☐	DATE 9-18-18
--	--	--	---	------------------------

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Csg	(E) Tubing
Pressure	0	0	N/A	0	700
Flow Characteristics					
Pull	Y/N ☒	Y/N ☒	Y/N ☐	Y/N ☒	CO2 ☐
Steady Flow	Y/N ☒	Y/N ☒	Y/N ☐	Y/N ☒	WTR ☒
Surges	Y/N ☒	Y/N ☒	Y/N ☐	Y/N ☒	GAS ☐
Down to nothing	Y/N ☒	Y/N ☒	Y/N ☐	Y/N ☒	Type of Fluid
Gas or Oil	Y/N ☒	Y/N ☒	Y/N ☐	Y/N ☒	Injected for
Water	Y/N ☒	Y/N ☒	Y/N ☐	Y/N ☒	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: [Signature]		OIL CONSERVATION DIVISION	
Printed name:		Entered into RBDMS	
Title:		Re-test	
E-mail Address:			
Date:	Phone:		
Witness: [Signature]			

INSTRUCTIONS ON BACK OF THIS FORM