

SEP 18 2018

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Mesquite SWD		API Number 30-025-43379-43379	
Property Name Paduca 6 SWD		Well No. #1 y	

1. Surface Location									
UL - Lot E00	Section 6	Township 26S	Range 32E	Feet from 2650	N/S Line S	Feet From 1175	E/W Line W	County LEA	

Well Status									
TA'D WELL YES	NO	SHUT-IN YES	NO	INJ SWD	OIL SWD	PRODUCER GAS	DATE 9-18-18		

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	0	N/A	0	1800
Flow Characteristics					
Pull	Y/N	Y/N	Y/N	Y/N	CO2 ✓
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR ✓
Surges	Y/N	Y/N	Y/N	Y/N	GAS ✓
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Injected for
Water	Y/N	Y/N	Y/N	Y/N	Water flow if applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: [Signature]		OIL CONSERVATION DIVISION	
Printed name:		Entered into RBDMS	
Title:		Re-test	
E-mail Address:			
Date:	Phone:		
Witness: [Signature]			