

HOBBES OCD

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

SEP 21 2018

BRADENHEAD TEST REPORT

RECEIVED

Operator Name <i>VADRIARD</i>		API Number <i>30-025-35124</i>
Property Name <i>Bimini 13 51</i>		Well No. <i>3</i>

Surface Location									
UL - Lot <i>X</i>	Section <i>13</i>	Township <i>17S</i>	Range <i>36E</i>		Feet from <i>1800</i>	N/S Line <i>S</i>	Feet From <i>1650</i>	E/W Line <i>W</i>	County <i>LA</i>

Well Status							
TA'D WELL YES ☒ NO ☒	SHUT-IN YES ☒ NO ☒	INJ	SWD	OIL ☒	GAS	DATE <i>9/21/17</i>	

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	ϕ	ϕ	—	<i>20</i>	<i>20</i>
Flow Characteristics					
Pull	<i>N</i>	<i>N</i>	<i>N</i>	<i>N</i>	CO2 —
Steady Flow	<i>N</i>	<i>N</i>	<i>N</i>	<i>N</i>	WTR —
Surges	<i>N</i>	<i>N</i>	<i>N</i>	<i>N</i>	GAS —
Down to nothing	<i>N</i>	<i>N</i>	<i>N</i>	<i>N</i>	Type of Fluid
Gas or Oil	<i>N</i>	<i>N</i>	<i>N</i>	<i>N</i>	Injected for
Water	<i>N</i>	<i>N</i>	<i>N</i>	<i>N</i>	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

*Blew surface into vac. Truck. Had Press. & Fluid
Blew down @ 10 sec. OK gmb
Compliance Resolved*

Signature: <i>Harvey Aronson</i>		OIL CONSERVATION DIVISION
Printed name:		Entered into RBDMS
Title:		Re-test
E-mail Address:		
Date: <i>9/21/17</i>	Phone:	<i>gmb</i>
Witness: <i>Gregory Brown</i>		

INSTRUCTIONS ON BACK OF THIS FORM