	UNITED STATE PARTMENT OF THE I UREAU OF LAND MANA	NTERIOR OCD Hobbs		FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018	
BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals. SUBMIT IN TRIPLICATE - Other instructions on page 2 1. Type of Well D Other				 Lease Serial No. NMNM3622 If Indian, Allottee or Tribe Name 	
SUBMIT IN T	TRIPLICATE - Other ins	tructions on page 2	Of	Unit or CA/Agreement, Name and	
1. Type of Well Soli Well Gas Well Oth	ner	\$		Name and No. COUT 18 FEDERAL 003	
2. Name of Operator CIMAREX ENERGY CO OF C	Contact: COLORA BO Mail: DEYLER			PI Well No. D-025-37893	
3a. Address 600 N. MARIENFELD, SUITE MIDLAND, TX 79701	600	3b. Phone No. (include area code) Ph: 432-687-3033	10. I T	Field and Pool or Exploratory Area ONTO; 7-RIVERS	
4. Location of Well <i>(Footage, Sec., T</i> Sec 18 T19S R34E SESW 81		ı)		County or Parish, State EA COUNTY, NM	
	······································				
12. CHECK THE AF	PPROPRIATE BOX(ES)	TO INDICATE NATURE O	F NOTICE, REP	ORT, OR OTHER DATA	
TYPE OF SUBMISSION			FACTION	·	
□ Notice of Intent	 Acidize Alter Casing 	 Deepen Hydraulic Fracturing 	 Production (S Reclamation 	INT TO PA	
bsequent Report	Casing Repair	New Construction	Recomplete	P&A NR	
Final Abandonment Notice	Change Plans Convert to Injection	Plug Back	Temporarily A Water Dispose		
testing has been completed. Final At determined that the site is ready for f	bandonment Notices must be fi inal inspection. 3.700': CIRC WELL W/	sults in a multiple completion or reco led only after all requirements, includ MIE 'PRES TEST CSG T(ompletion in a new int ling reclamation, have	been completed and the operator h	
testing has been completed. Final At determined that the site is ready for fi 09/30/17: SET 4-1/2" CIBP @ 50 SXS.CMT. @ 3,700'; WOC 10/01/17: TAG CMT. PLUG @ PUMP 30 SXS.CMT. @ 1,639 WOC	oandonment Notices must be fi inal inspection. <u>3,700';</u> CIRC. WELL W/ <u>X TAG CMT @ 3,247'(</u>) 2,749'(PLUG HAD FAL 2,749'(PLUG HAD FAL 2,749'(PLUG HAD FAL 2,749'(PLUG HAD FAL 0,749'(PLUG HAD FAL 2,749'(PLUG HAD FAL 0,749'(PLUG HAD FAL 2,749'(PLUG HAD F	sults in a multiple completion or reco led only after all requirements, includ M.L.F.; PRES. TEST CSG. TO OK'D BY BLM); P <u>UMP 25 SX</u> LEN); PRES. TEST CSG. TO G CMT. @ 1,350' (OK'D BY B QZ. HOLES @ 63'; ATTEMPT 36-3'(PER BLM); DIG OUT X	ompletion in a new int ling reclamation, have 0 500# - HELD O <u>5.CMT. @ 1.639</u> '; 750# - HELD FOI LM); P <u>UMP 25 S</u> TO EST. INJ. RA CUT OFF WELLH ARKER.	erval, a Form 3160-4 must be filed been completed and the operator h WOC. 30TMINS.; S.CMT. @ 481'; NTE - PRES. IEAD 3' B.G.L.;	
testing has been completed. Final Al determined that the site is ready for fi 09/30/17: SET <u>4-1/2" CIBP</u> 50 SXS.CMT. @ 3,700'; WOC 10/01717: TAG CMT. PLUG @ PUMP 30 SXS.CMT. @ 1,639 WOC UP 10 500# X HOLD; MIX X WELD ON STEEL PLATE TO WELL PLUGGED AND ABAN	oandonment Notices must be fi inal inspection. <u>3,700';</u> CIRC. WELL W/ <u>X TAG CMT @ 3,247'(</u>) 2,749'(PLUG HAD FAL 2,749'(PLUG HAD FAL 2,749'(PLUG HAD FAL 2,749'(PLUG HAD FAL 0,749'(PLUG HAD FAL 2,749'(PLUG HAD FAL 0,749'(PLUG HAD FAL 2,749'(PLUG HAD F	sults in a multiple completion or reco led only after all requirements, includ M.L.F.; PRES. TEST CSG. TO OK'D BY BLM); P <u>UMP 25 SX</u> LEN); PRES. TEST CSG. TO G CMT. @ 1,350' (OK'D BY B QZ. HOLES @ 63'; ATTEMPT 36-3'(PER BLM); DIG OUT X	ompletion in a new int ling reclamation, have 0 500# - HELD O S.CMT. @ 1.639'; 750# - HELD FOI LM); PUMP 25 S TO EST. INJ. RA CUT OFF WELLH ARKER.	erval, a Form 3160-4 must be filed been completed and the operator h WOC. 300MINS.; XS.CMT. @ 481'; ATE - PRES. IEAD 3' B.G.L.; PTED FOR RECORI	
testing has been completed. Final Al determined that the site is ready for fi 09/30/17: SET <u>4-1/2" CIBP</u> 50 SXS.CMT. @ 3,700'; WOC 10/01717: TAG CMT. PLUG @ PUMP 30 SXS.CMT. @ 1,639 WOC UP 10 500# X HOLD; MIX X WELD ON STEEL PLATE TO WELL PLUGGED AND ABAN	bandonment Notices must be fi inal inspection. <u>3,700'</u> ; CIRC. WELL W/ <u>2,749'</u> (PLUG HAD FAL <u>2,749'</u> (PLUG HAD FAL <u>2,749'</u> (PLUG HAD FAL <u>2,749'</u> (PLUG HAD FAL <u>2,749'</u> (PLUG HAD FAL <u>0,749'</u> (PLUG HAD	sults in a multiple completion or reco led only after all requirements, include M.L.F.; PRES. TEST CSG. TO OK'D BY BLM); P <u>UMP 25 SX3</u> LEN); PRES. TEST CSG. TO <u>G CMT. @ 1,350'</u> (OK'D BY B <u>QZ. HOLES @ 63'</u> , ATTEMPT <u>36'-3'</u> (PER BLM); DIG OUT X OW GROUND DRY HOLE M/ RECLAMATIO	OMPLETION IN A NEW INT SOUTH - HELD ON SOUTH - HELD ON SOUTH - HELD FOR SOUTH - HELD FOR SOUTH OFF WELLH ARKER. ON ACCEN	erval, a Form 3160-4 must be filed been completed and the operator h WOC:- X30TMINS.; XS.CMT. @ 481'; ATE - PRES. IEAD 3' B.G.L.; PTED FOR RECORI SEP 1 4 2018	
testing has been completed. Final Al determined that the site is ready for fi 09/30/17: SET <u>4-1/2" CIBP</u> 50 SXS.CMT. @ 3,700'; WOO 10/01717: T <u>AG CMT. PLUG @</u> PUMP 30 SXS.CMT. @ 1,639 WOC TAG CMT. @ 106'((UP TO 500# X HOLD; MIX X WELD ON STEEL PLATE TO WELL PLUGGED AND ABAN RECLAM	andonment Notices must be fi inal inspection. <u>3,700';</u> CIRC. WELL W/ <u>2,749'(PLUG HAD FAL</u> <u>2,749'(PLUG HAD FAL</u> <u>2,749'(PLUG HAD FAL</u> <u>2,749'(PLUG HAD FAL</u> <u>2,749'(PLUG HAD FAL</u> <u>2,749'(PLUG 3,247'()</u> <u>3,700';</u> CIRC. WELL <u>1,749'(PLUG 3,247'()</u> <u>3,749'(PLUG 3,247'()</u>	sults in a multiple completion or reco led only after all requirements, includ M.L.F.; PRES. TEST CSG. TO OK'D BY BLM); P <u>UMP 25 SX:</u> LEN); PRES. TEST CSG. TO <u>G CMT. @</u> 1,350' (OK'D BY B <u>QZ. HOLES @ 63':</u> ATTEMPT <u>36'-3'</u> (PER BLM); DIG OUT X OW GROUND DRY HOLE M RECLAMATION DUE <u>4.2.1</u>	ompletion in a new int ling reclamation, have 0 500# - HELD O S.CMT. @ 1.639'; 750# - HELD FOI LM); PUMP 25 S TO EST. INJ. RACUT OFF WELLH ARKER. ON II Information Syst it to the Hobbs	erval, a Form 3160-4 must be filed been completed and the operator h WOC: 300MINS.; XS.CMT. @ 481'; NTE - PRES. IEAD 3' B.G.L.; PTED FOR RECORI SFP 1 4 2018	
testing has been completed. Final At determined that the site is ready for f 09/30/17: SET 4-1/2" CIBP @ 50 SXS.CMT. @ 3,700'; WOC TU/UT/17: TAG CMT. PLUG @ PUMP 30 SXS CMT. @ 1,639 WOC TAG CMT. @ 106'((UP TO 500# X HOLD; MIX X WELD ON STEEL PLATE TO WELL PLUGGED AND ABAN RECLAM	andonment Notices must be fi inal inspection. 3.700'; CIRC. WELL W/ X TAG CMT @ 3.247'(0) 2.749'(PLUG HAD FAL 2(PER BLM); WOC X TA OK'D BY BLM); PERF. S CIRC. 10 SXS CMT. @ 5 CSGS. X INSTALL BEL DONED 10/02/17. MATION PROCEDURE ATTACHED 5 true and correct. Electronic Submission # For CIMAREX EN EYLER	sults in a multiple completion or reco led only after all requirements, include M.L.F.; PRES. TEST CSG. TO OK'D BY BLM); P <u>UMP 25 SX</u> LEN); PRES. TEST CSG. TO <u>G CMT. @ 1,350'</u> (OK'D BY B <u>QZ. HOLES @ 63'</u> ; ATTEMPT <u>36-3'</u> (PER BLM); DIG OUT X OW GROUND DRY HOLE M/ RECLAMATI DUE <u>4.2.1</u> 390718 verified by the BLM We ERGY CO OF COLORADO, ser	ompletion in a new int ling reclamation, have 0 500# - HELD O S.CMT. @ 1.639'; 750# - HELD FOI LM); PUMP 25 S TO EST. INJ. RACUT OFF WELLH ARKER. ON II Information Syst it to the Hobbs BURE	erval, a Form 3160-4 must be filed been completed and the operator h WOC:- X30TMINS.; XS.CMT. @ 481'; ATE - PRES. IEAD 3' B.G.L.; PTED FOR RECORI SEP 1 4 2018	
testing has been completed. Final Al determined that the site is ready for f 09/30/17: SET 4-1/2" CIBP @ 50 SXS.CMT. @ 3,700'; WOO T0/01717: TAG CMT. PLUG @ PUMP 30 SXS CMT. @ 1,639 WOC TAG CMT. @ 106'((UP TO 500# X HOLD; MIX X WELD ON STEEL PLATE TO WELL PLUGGED AND ABAN RECLAM	andonment Notices must be fi inal inspection. 3.700'; CIRC. WELL W/ X TAG CMT_@ 3.247'(2.749'(PLUG HAD FAL (PER*BLM); WOC X TA OK'D BY BLM); PERF. S CIRC. 10 SXS.CMT.@ S CSGS. X INSTALL BEL IDONED 10/02/17. MATION PROCEDURE ATTACHED Strue and correct. Electronic Submission # For CIMAREX EN EYLER Submission)	sults in a multiple completion or reco led only after all requirements, included M.L.F.; PRES. TEST CSG. TO OK'D BY BLM); P <u>UMP 25 SX</u> LEN); PRES. TEST CSG. TO <u>G CMT. @ 1,350'</u> (OK'D BY B <u>QZ. HOLES @ 63'</u> ; ATTEMPT <u>36-3'</u> (PER BLM); DIG OUT X OW GROUND DRY HOLE M/ RECLAMATI DUE <u>4.2.1</u> 390718 verified by the BLM We ERGY CO OF COLORADO, sen Title AGENT	ompletion in a new int ling reclamation, have 0 500# - HELD O <u>S.CMT. @ 1.639</u> ; 750# - HELD FOI LM); PUMP 25 S TO EST. INJ. RACUT OFF WELLF ARKER. ON II Information Syst t to the Hobbs BURE OUT	erval, a Form 3160-4 must be filed been completed and the operator h WOC:- X30TMINS.; XS.CMT. @ 481'; ATE - PRES. IEAD 3' B.G.L.; PTED FOR RECORI SEP 1 4 2018	
testing has been completed. Final Al determined that the site is ready for f 09/30/17: SET 4-1/2" CIBP @ 50 SXS.CMT. @ 3,700'; WOO T0/01717: TAG CMT. PLUG @ PUMP 30 SXS CMT. @ 1,639 WOC TAG CMT. @ 106'((UP TO 500# X HOLD; MIX X WELD ON STEEL PLATE TO WELL PLUGGED AND ABAN RECLAM	andonment Notices must be fi inal inspection. 3.700'; CIRC. WELL W/ X TAG CMT_@ 3.247'(2.749'(PLUG HAD FAL (PER*BLM); WOC X TA OK'D BY BLM); PERF. S CIRC. 10 SXS.CMT.@ S CSGS. X INSTALL BEL IDONED 10/02/17. MATION PROCEDURE ATTACHED Strue and correct. Electronic Submission # For CIMAREX EN EYLER Submission)	sults in a multiple completion or reco led only after all requirements, include M.L.F.; PRES. TEST CSG. TO OK'D BY BLM); P <u>UMP 25 SX</u> LEN); PRES. TEST CSG. TO G CMT. @ 1,350' (OK'D BY B QZ. HOLES @ 63'; ATTEMPT 26'-3'(PER BLM); DIG OUT X OW GROUND DRY HOLE M/ W GROUND DRY HOLE M/ IN UF 4.2.1 2 390718 verified by the BLM We ERGY CO OF COLORADO, sen Title AGENT Date 10/04/2	ompletion in a new int ling reclamation, have 0 500# - HELD O <u>S.CMT. @ 1.639</u> ; 750# - HELD FOI LM); PUMP 25 S TO EST. INJ. RACUT OFF WELLF ARKER. ON II Information Syst t to the Hobbs BURE OUT	erval, a Form 3160-4 must be filed been completed and the operator h WOC:- X30TMINS.; XS.CMT. @ 481'; ATE - PRES. IEAD 3' B.G.L.; PTED FOR RECORI SEP 1 4 2018	
testing has been completed. Final Aldetermined that the site is ready for ff 09/30/17: SET 4-1/2" CIBP @ 50 SXS.CMT. @ 3,700'; WOC 10/01717: TAG CMT. PLUG @ PUMP 30 SXS.CMT. @ 1,639 WOC TAG.CMT. @ 106'((UP TO 500# X HOLD; MIX X WELD ON STEEL PLATE TO WELL PLUGGED AND ABAN RECLAM	andonment Notices must be fi inal inspection. 3.700'; CIRC. WELL W/ X TAG CMT_@ 3.247'(2.749'(PLUG HAD FAL 2(PER BLM); WOC X TA OK'D BY BLM); PERF, S CIRC. 10 SXSCMT.@ S CSGS. X INSTALL BEL DONED 10/02/17. MATION PROCEDURE ATTACHED Strue and correct. Electronic Submission # For CIMAREX EN EYLER Submission) THIS SPACE FO	sults in a multiple completion or reco led only after all requirements, included M.L.F.; PRES. TEST CSG. TO OK'D BY BLM); P <u>UMP 25 SX</u> LEN); PRES. TEST CSG. TO <u>G CMT. @ 1,350'</u> (OK'D BY B <u>QZ. HOLES @ 63'</u> ; ATTEMP1 <u>36'-3'(PER BLM); DIG OUT X</u> OW GROUND DRY HOLE M/ RECLAMATION DUE 4.2.1 2 ABOOT 18 verified by the BLM We ERGY CO OF COLORADO, sen Title AGENT Date 10/04/2 DR FEDERAL OR STATE	ompletion in a new int ling reclamation, have 0 500# - HELD O <u>S.CMT. @ 1.639</u> ; 750# - HELD FOI LM); PUMP 25 S TO EST. INJ. RACUT OFF WELLF ARKER. ON II Information Syst t to the Hobbs BURE OUT	erval, a Form 3160-4 must be filed been completed and the operator h WOC:- X30TMINS.; XS.CMT. @ 481'; ATE - PRES. IEAD 3' B.G.L.; PTED FOR RECORI SFP 1 4 2018 EMPLOY A D OF LAND MANAGEMENT RLSBAD FIELD OFFICE	
testing has been completed. Final At determined that the site is ready for f 09/30/17: SET 4-1/2" CIBP @ 50 SXS.CMT. @ 3,700'; WOO TU/UT/17: TAG CMT. PLUG @ PUMP 30 SXS CMT. @ 1,639 WOC TAG CMT. @ 106'((UP TO 500# X HOLD; MIX X WELD ON STEEL PLATE TO WELL PLUGGED AND ABAN RECLAM 14. 1 hereby certify that the foregoing is Name (<i>Printed/Typed</i>) DAVID A I Signature (Electronic S Approved By	andonment Notices must be fi inal inspection. 3.700'; CIRC. WELL W/ X TAG CMT @ 3.247'(2.749'(PLUG HAD FAL (PER BLM); WOC X TA OK'D BY BLM); PERF. S CIRC. 10 SXS.CMT.@ 3 CSGS. X INSTALL BEL DONED 10/02/17. MATION PROCEDURE ATTACHED Submission # For CIMAREX EN EYLER Submission) THIS SPACE F(d. Approval of this notice doe: aitable title to those rights in this ict operations thereon. U.S.C. Section 1212, make it a	sults in a multiple completion or reco led only after all requirements, includ M.L.F.; PRES. TEST CSG. TO OK'D BY BLM); P <u>UMP 25 SX</u> LEN); PRES. TEST CSG. TO G CMT. @ 1,350' (OK'D BY B QZ. HOLES @ 63'; ATTEMPT 26'-3'(PER BLM); DIG OUT X OW GROUND DRY HOLE M/ W GROUND DRY HOLE M/ DW GROUND DRY HOLE M/ W GROUND DRY HOLE M/ DW GROU	ompletion in a new int ling reclamation, have 0 500# - HELD O S.CMT. @ 1.639'; 750# - HELD FOI LM); PUMP 25 S TO EST. INJ. RACUT OFF WELLF ARKER. ON II Information Syst t to the Hobbs BURE 017 OFFICE USE	erval, a Form 3160-4 must be filed been completed and the operator h WOC. 30TMINS.; XS.CMT. @ 481'; ATE - PRES. IEAD 3' B.G.L.; PTED FOR RECORI SFP 1 4 2018 ENDIFICE AU OF LAND MANAGEMENT RLSBAD FIELD OFFICE Date	



S

United States Department of the Interior

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 E. Greene St. Carlsbad, New Mexico 88220-6292 www.blm.gov/nm



In Reply Refer To: 1310

Reclamation Objectives and Procedures

Reclamation Objective: Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses. At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land and water are restored.

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its predisturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any and all contaminants, scrap/trash, equipment, pipelines and powerlines. Strip and remove caliche, contour the location to blend with the surrounding landscape, redistribute the native soils, provide erosion control as needed, rip and seed as specified in the original APD COA. This will apply to well pads, facilities, and access roads. Barricade access road at the starting point. If reserve pits have not reclaimed due to salts or other contaminants, submit a plan for approval, as to how you propose to provide adequate restoration of the pit area.

- The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of Operations must include adequate measures for stabilization and reclamation of disturbed lands. Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD process as per Onshore Oil and Gas Order No. 1.
- 2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). For final reclamation, the appropriate time for submittal would be when filing the Notice of Intent, or the Subsequent Report of Abandonment, Sundry Notices and Reports on Wells (Form 3160-5). Interim reclamation is to be completed within 6 months of well completion, and final reclamation is to be completed within 6 months.
- 3. The operator must file a Subsequent Report Plug and Abandonment (Form 3160-5) following the plugging of a well.
- 4. Previous instruction had you waiting for a BLM specialist to inspect the location and provide you with reclamation requirements. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD. If you have issues or concerns, contact a BLM specialist to assist you. It would be in your interest to have a BLM specialist look at the location and access road prior to the removal of reclamation

equipment to ensure that it meets BLM objectives. Upon conclusion submit a Form 3160-5, Subsequent Report of Reclamation. This will prompt a specialist to inspect the location to verify work was completed as per approved plans.

- 5. The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.
- 6. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the BLM objectives have been met submit a Final Abandonment Notice (FAN), Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection.
- 7. At this time the BLM specialist will inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, releasing the operator of any further liability of the location and/or access road. If the location and/or access road have not achieved the objective, you will be notified as to additional work needed or additional time being needed to achieve the objective.

If there are any questions, please feel free to contact any of the following specialists:

Jim Amos Supervisory Petroleum Engineering Tech 575-234-5909, 575-361-2648 (Cell)

Arthur Arias Environmental Protection Specialist 575-234-6230

Henryetta Price Environmental Protection Specialist 575-234-5951

Shelly Tucker Environmental Protection Specialist 575-234-5979

Trishia Bad Bear, Hobbs Field Station Natural Resource Specialist 575-393-3612